

Site Photos (05-073-06349) 7/31/2014

Photo #1



Photo #2 Weed growth on South side of location





Photo #3 Weed growth on South side of location.



Photo #4 Guy line marker on Southeast corner of location.





Photo #5 Animal burrows through the berms.



Photo #6 Animal burrows through the berms.





Photo #7 Animal burrows through the berms.



Photo #8 Rills off of slope on South side of location.

