

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:  
07/23/2014

Document Number:  
667200235

Overall Inspection:

**VIOLATION**

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>219170</u>	<u>312161</u>	<u>SCHURE, KYM</u>	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number:	<u>10380</u>
Name of Operator:	<u>BENCHMARK ENERGY LLC</u>
Address:	<u>PO BOX 8747</u>
City:	<u>PRATT</u> State: <u>KS</u> Zip: <u>67124</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
QUINT, CRAIG		craig.quint@state.co.us	
Nash, Jerry	(316) 218-8184	jerry@benchmarkenergy.us	All Inspections
Ferrell, LaDawn	(620) 672-3800	lferrell@profsecservices.com	All Inspections

**Compliance Summary:**

QtrQtr:	<u>SESW</u>	Sec:	<u>1</u>	Twp:	<u>8N</u>	Range:	<u>54W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/08/2013	664001187	TA	TA	SATISFACTOR Y			No
07/09/2012	663300292	TA	TA	<b>ACTION REQUIRED</b>	I		No
06/16/2011	200312782	MI	TA	SATISFACTOR Y			No
05/03/2011	200309692	RT	TA	SATISFACTOR Y			No
05/24/2010	200253086	RT	TA	SATISFACTOR Y			No
08/04/2009	200215932	RT	TA	SATISFACTOR Y			No
04/22/2008	200130646	RT	TA	SATISFACTOR Y			No
06/20/2007	200115799	RT	TA	SATISFACTOR Y		Pass	No
06/08/2006	200091666	MI	TA	SATISFACTOR Y		Pass	No
07/05/2005	200074133	RT	TA	SATISFACTOR Y		Pass	No
06/15/2004	200055915	RT	TA	SATISFACTOR Y		Pass	No
04/02/2003	200036995	RT	TA	SATISFACTOR Y		Pass	No
07/18/2002	200028852	RT	TA	SATISFACTOR Y	P	Pass	No

Inspector Name: SCHURE, KYM

07/26/2001	200018312	MI	TA	SATISFACTOR Y	Pass	No
08/03/2000	200008439	RT	SI	SATISFACTOR Y	Pass	No

**Inspector Comment:**

Within (5) days of receipt of this Inspection Report, submit to COGCC a detailed written plan and schedule of completion to resolve "Action Required" items listed in this report. Submit to COGCC "AS BUILT" with Form 4 Sundry including As-Built Location Policy and Rule 215. "Violation" items listed on this report are dated on day of Inspection and require immediate resolution.

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
219170	WELL	TA	01/01/1999	ERIW	075-06000	NW GRAYLIN D-SAND UNIT 6-W	TA	<input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access		No lease road		

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	ACTION REQUIRED	Invalid signage	Install sign to comply with rule 210.	08/11/2014

Emergency Contact Number (S/A/V): VIOLATION

Corrective Date: 07/23/2014

Comment: NO emergency contact information

Corrective Action: Install sign to comply with Rule 210.

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
DEBRIS	ACTION REQUIRED	Pipe and valve laying on surface at wellhead	Remove all debris	08/11/2014

**Spills:**

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
	SATISFACTORY			

<b>Equipment:</b>					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Other	0	SATISFACTORY			

<b>Venting:</b>	
Yes/No	Comment

<b>Flaring:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 219170

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/A/V:** \_\_\_\_\_ **Comment:**

**CA:**  **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/A/V:** \_\_\_\_\_ **Comment:**

**CA:**  **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Facility**

Facility ID: 219170 Type: WELL API Number: 075-06000 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder:

S/A/V: VIOLATION CA Date: 07/23/2014

CA: See full Inspection Report for corrective actions and corrective action dates

Comment:

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS: Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? CM

CA CA Date

Waste Material Onsite? CM

CA CA Date

Unused or unneeded equipment onsite? CM

CA CA Date

Pit, cellars, rat holes and other bores closed? CM

CA CA Date

Guy line anchors removed? CM

CA CA Date

Guy line anchors marked? CM

CA CA Date

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment:

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment:

Corrective Action:  Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

S/AV: SATISFACTOR \_\_\_\_\_ Corrective Date: \_\_\_\_\_  
 Y \_\_\_\_\_

Comment: No surface erosion from stormwater runoff observed

CA:

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
667200285	Signage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3400977">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3400977</a>
667200286	Debris	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3400978">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3400978</a>