

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
07/31/2014

Document Number:
667200313

Overall Inspection:

VIOLATION

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>219493</u>	<u>312204</u>	<u>SCHURE, KYM</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10380</u>
Name of Operator:	<u>BENCHMARK ENERGY LLC</u>
Address:	<u>PO BOX 8747</u>
City:	<u>PRATT</u> State: <u>KS</u> Zip: <u>67124</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Ferrell, LaDawn	(620) 672-3800	lferrell@profsecservices.com	All Inspections
Nash, Jerry	(316) 218-8184	jerry@benchmarkenergy.us	All Inspections
QUINT, CRAIG		craig.quint@state.co.us	
AXELSON, JOHN		john.axelson@state.co.us	

Compliance Summary:

QtrQtr: NWSW Sec: 19 Twp: 9N Range: 53W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/07/2013	664001194	SI	SI	SATISFACTOR Y			No
08/15/2012	663300429	IJ	IJ	SATISFACTOR Y	I		No
08/01/2012	663300348	IJ	IJ	ACTION REQUIRED			No
06/16/2011	200312769	MI	SI	ACTION REQUIRED			Yes
07/16/2010	200262951	RT	AC	SATISFACTOR Y			No
06/18/2009	200213160	RT	AC	SATISFACTOR Y			No
04/08/2008	200130207	RT	AC	SATISFACTOR Y			No
06/20/2007	200115795	RT	AC	SATISFACTOR Y		Pass	No
06/08/2006	200091675	MI	AC	SATISFACTOR Y		Pass	No
07/05/2005	200074156	RT	SI	SATISFACTOR Y		Pass	No
06/15/2004	200055902	RT		SATISFACTOR Y		Pass	No
04/02/2003	200037000	RT	AC	SATISFACTOR Y		Pass	No

Inspector Name: SCHURE, KYM

07/15/2002	200028843	RT	AC	SATISFACTOR Y	P	Pass	No
07/31/2001	200018295	MI	AC	SATISFACTOR Y		Pass	No
06/20/2000	200011967	RT	SI	SATISFACTOR Y		Pass	No
06/20/2000	200012373	RT	AC	SATISFACTOR Y		Pass	No
03/20/1995	500153088	MI	AC				

Inspector Comment:

Within (5) days of receipt of this inspection report, submit to COGCC a detailed written plan and schedule of completion to resolve "Action Required" items. "Violation" items require immediate resolution and have corrective action dates on day of inspection. Submit "As Built" Sundry Form 4 with AS-BUILT Location Policy and Rule 215.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
219493	WELL	SI	04/26/2013	ERIW	075-06414	MOUNT HOPE UNIT W-3	SI	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access		No lease road		

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	ACTION REQUIRED		Install sign to comply with rule 210.	08/11/2014

Emergency Contact Number (S/A/V): VIOLATION Corrective Date: 07/31/2014

Comment: _____

Corrective Action: Install sign with valid emergency contact information

Spills:

Type	Area	Volume	Corrective action	CA Date
Produced Water	WELLHEAD	> 5 bbls	Remove/remediate affected soils exhibiting vegetation kill.	07/31/2014

Multiple Spills and Releases?

Equipment:					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Other	0	SATISFACTORY			
Ancillary equipment	0	SATISFACTORY			

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 219493

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/A/V: _____ **Comment:**

CA: **Date:** _____

Wildlife BMPs:

S/A/V: _____ **Comment:**

CA: **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 219493 Type: WELL API Number: 075-06414 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/A/V: VIOLATION CA Date: 07/31/2014
CA: See full inspection report for details
Comment: _____

Environmental

Spills/Releases:

Type of Spill: WATER Description: Vegetation kill Estimated Spill Volume: 5
Comment: Forwarding to COGCC Environmental
Corrective Action: Remove/remediate affected soils and vegetation kill Date: 07/31/2014
Reportable: YES GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					

S/A/V: **ACTION REQUIRED** Corrective Date: **08/11/2014**

Comment: _____

CA: **Remove/remediate affected soils exhibiting vegetation kill. Install stormwater BMP's.**

Pits: NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
667200314	Well site - Vegetation kill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3401010
667200315	Well head - signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3401011
667200316	Unmarked deadman	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3401012
667200317	Unmarked deadman	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3401013