

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
08/06/2014

Document Number:
673705199

Overall Inspection:

ACTION REQUIRED

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>236765</u>	<u>317139</u>	<u>Sherman, Susan</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10110</u>
Name of Operator:	<u>GREAT WESTERN OPERATING COMPANY LLC</u>
Address:	<u>1801 BROADWAY #500</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Bradley, Sam	(970) 286-3426	sbradley@gwogco.com	
DONATO, SCOTT	(303) 398-0537	SDONATO@GWOGCO.COM	
Musgrave, Tim	(970) 768-6097	tmusgrave@gwogco.com	
KOEHLER, BOB		bob.koehler@state.co.us	

Compliance Summary:

QtrQtr: NWNE Sec: 30 Twp: 1S Range: 56W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/29/2013	664001162	SI	SI	SATISFACTOR Y			No
06/28/2013	664001092	SI	SI	SATISFACTOR Y			No
06/25/2013	664001090			SATISFACTOR Y			No
02/11/2013	664000756	SI	SI	ACTION REQUIRED			No
07/16/2012	663400616	SI	AC	ACTION REQUIRED	P		No
04/01/2011	200306300	RT	AC	SATISFACTOR Y			No
07/14/2010	200262639	MI	AC	SATISFACTOR Y			No
06/24/2010	200258526	RT	AC	SATISFACTOR Y			No
06/22/2009	200213554	RT	AC	SATISFACTOR Y			No
04/10/2007	200109270	PR	SI	SATISFACTOR Y		Pass	No
04/10/2006	200089412	RT	AC	SATISFACTOR Y		Pass	No
04/19/2005	200070150	MI	SI	SATISFACTOR Y		Pass	No

Inspector Name: Sherman, Susan

03/14/2005	200068623	CC	SI	ACTION REQUIRED		Fail	No
05/23/2003	200039651	PR	TA	ACTION REQUIRED		Fail	Yes
03/12/2002	200024826	ID	TA	ACTION REQUIRED		Fail	Yes

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
159114	UIC DISPOSAL	AC	04/15/2004		-	GREAT WESTERN FLESSNER 14	AC	<input checked="" type="checkbox"/>
236765	WELL	PR	12/04/2013	DSPW	121-09259	FLESSNER 14	SI	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
BATTERY	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WEEDS	ACTION REQUIRED		Control weeds.	09/05/2014

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 236765

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/A/V: _____ **Comment:**

CA: **Date:** _____

Wildlife BMPs:

S/A/V: _____ **Comment:**

CA: **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 159114 Type: UIC API Number: - Status: AC Insp. Status: AC

Facility ID: 236765 Type: WELL API Number: 121-09259 Status: PR Insp. Status: SI

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg -2 in
(e.g. 30 psig or -30" Hg)

Previous Test Pressure _____ MPP _____
Inj Zone: JSND

TC: Pressure or inches of Hg 0

Previous Test Pressure _____ Last MIT: 07/29/2013

Brhd: Pressure or inches of Hg _____

Previous Test Pressure _____ AnnMTRReq: _____

Comment: Slight vacuum on casing that died immediately. Pump down for maintainance. Bob Koehler is checking on status of this well.

Method of Injection: GRAVITY FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: wheat field

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Inspector Name: Sherman, Susan

Compaction	Pass	Compaction	Pass			
S/A/V: SATISFACTOR		Corrective Date: _____				
Y		_____				
Comment: _____						
CA: _____						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673705206	WO Flessner 14 IJ well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3402930
673705207	WO Flessner 14 IJ wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3402931
673705208	WO Flessner 14 IJ well DM and weeds	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3402932
673705209	WO Flessner 14 IJ Bat sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3402933
673705210	WO Flessner 14 IJ Bat sign 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3402934
673705211	WO Flessner 14 IJ Bat tank labels	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3402935
673705212	WO Flessner 14 IJ Bat tank labels 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3402936
673705213	WO Flessner 14 IJ Bat tank berms	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3402937