

Inspector Name: Hughes, Jim

**FORM  
INSP**

Rev  
05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

08/01/2014

Document Number:

674900103

Overall Inspection:

SATISFACTORY

**FIELD INSPECTION FORM**

|                     |             |        |                 |                          |             |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection       | 2A Doc Num: |
|                     | 216488      | 326435 | Hughes, Jim     | <input type="checkbox"/> |             |

**Operator Information:**

OGCC Operator Number: 96705

Name of Operator: WPX ENERGY PRODUCTION LLC

Address: P O BOX 3102 MS-25-2

City: TULSA State: OK Zip: 74101

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED  
☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name     | Phone          | Email                        | Comment    |
|------------------|----------------|------------------------------|------------|
| LABOWSKIE, STEVE |                | steve.labowskie@state.co.us  |            |
| Heil, Mark       |                | mark.heil@wpxenergy.com      |            |
| Maclaren, Joe    |                | joe.maclaren@state.co.us     |            |
| FISCHER, ALEX    |                | alex.fischer@state.co.us     |            |
| Granillo, Lacey  | (505)-333-1816 | lacey.granillo@wpxenergy.com | Permitting |

**Compliance Summary:**

QtrQtr: SENV Sec: 10 Twp: 33N Range: 8W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 05/05/2009 | 200209622 | PR         | PR          | SATISFACTORY<br>Y             |          |                | No              |
| 01/18/2006 | 200087902 | PR         | PR          | SATISFACTORY<br>Y             |          | Pass           | No              |
| 01/27/2004 | 200052450 | PR         | PR          | SATISFACTORY<br>Y             |          | Pass           | No              |
| 02/11/2003 | 200036319 | PR         | PR          | SATISFACTORY<br>Y             |          | Pass           | No              |
| 07/17/2001 | 200019537 | PR         | PR          | SATISFACTORY<br>Y             |          | Pass           | No              |
| 02/15/2000 | 200004442 | PR         | PR          | SATISFACTORY<br>Y             |          | Pass           | No              |
| 03/04/1998 | 500150705 | PR         | PR          |                               |          | Pass           | No              |
| 01/28/1998 | 500150706 | PR         | PR          |                               |          | Pass           | No              |
| 01/28/1998 | 500150704 | PR         | PR          |                               |          | Pass           | No              |

**Inspector Comment:**

On August 1, 2014 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the WPX Ignacio 33-8 #27. Please refer to document #200209622 for the most recent field inspection report for this facility.

**Related Facilities:**

Inspector Name: Hughes, Jim

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|-------------------------------------|
| 216488      | WELL | PR     | 01/10/2012  | GW         | 067-08094 | IGNACIO 33-8 #027 | EI          | <input checked="" type="checkbox"/> |

**Equipment:**Location Inventory

|                             |                        |                     |                         |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____     | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____  | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____      | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____      | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location****Lease Road:**

| Type   | Satisfactory/Action Required | comment | Corrective Action | Date |
|--------|------------------------------|---------|-------------------|------|
| Access | SATISFACTORY                 |         |                   |      |

**Signs/Marker:**

| Type                 | Satisfactory/Action Required | Comment                        | Corrective Action                     | CA Date    |
|----------------------|------------------------------|--------------------------------|---------------------------------------|------------|
| TANK LABELS/PLACARDS | ACTION REQUIRED              | PBV has no labels or placards. | Install sign to comply with rule 210. | 09/08/2014 |
| WELLHEAD             | SATISFACTORY                 |                                |                                       |            |

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?**Fencing/:**

| Type  | Satisfactory/Action Required | Comment  | Corrective Action | CA Date |
|-------|------------------------------|--|-------------------|---------|
| OTHER | SATISFACTORY                 | Chemical container labeled SLCI 4 scale inhibitor within fenced enclosure. |                   |         |

**Equipment:**

| Type                      | # | Satisfactory/Action Required | Comment         | Corrective Action | CA Date |
|---------------------------|---|------------------------------|-----------------|-------------------|---------|
| Ancillary equipment       | 1 | SATISFACTORY                 | Electric supply |                   |         |
| Ancillary equipment       | 1 | SATISFACTORY                 | Telemetry       |                   |         |
| Deadman # & Marked        | 4 | SATISFACTORY                 |                 |                   |         |
| Bird Protectors           | 2 | SATISFACTORY                 |                 |                   |         |
| Gas Meter Run             | 2 | SATISFACTORY                 |                 |                   |         |
| Vertical Heated Separator | 2 | SATISFACTORY                 |                 |                   |         |

Inspector Name: Hughes, Jim

|                                |                              |  |   |                       |                             |
|--------------------------------|------------------------------|--|---|-----------------------|-----------------------------|
| <b>Facilities:</b>             |                              | <input type="checkbox"/> New Tank          |   | Tank ID: _____        |                             |
| Contents                       | #                            | Capacity                                   | Type                                    | SE GPS                |                             |
| PRODUCED WATER                 | 1                            | <100 BBLS                                  | PBV STEEL                               | 37.121404,-107.708191 |                             |
| S/AV:                          | ACTION REQUIRED              |  | Comment: PBV has no labels or placards. |                       |                             |
| Corrective Action:             |                              | Install signs and placards per Rule 210.d. |   |                       | Corrective Date: 09/08/2014 |
| <b>Paint</b>                   |                              |  |   |                       |                             |
| Condition                      | Adequate                     |  |   |                       |                             |
| Other (Content) _____          |                              |  |   |                       |                             |
| Other (Capacity) 95 bbl. _____ |                              |  |   |                       |                             |
| Other (Type) _____             |                              |  |   |                       |                             |
| <b>Berms</b>                   |                              |  |   |                       |                             |
| Type                           | Capacity                     | Permeability (Wall)                        | Permeability (Base)                     | Maintenance           |                             |
| Metal                          | Adequate                     | Walls Sufficient                           | Base Sufficient                         | Adequate              |                             |
| Corrective Action              |                              |  |   |                       | Corrective Date             |
| Comment                        |                              |  |   |                       |                             |
| <b>Venting:</b>                |                              |  |   |                       |                             |
| Yes/No                         |                              | Comment                                    |   |                       |                             |
| NO                             |                              |  |   |                       |                             |
| <b>Flaring:</b>                |                              |  |   |                       |                             |
| Type                           | Satisfactory/Action Required |  | Comment                                 | Corrective Action     | CA Date                     |
|                                |                              |  |   |                       |                             |

Inspector Name: Hughes, Jim

**Predrill**

Location ID: 216488

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

**Surface Owner Contact Information:**

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:**

**Summary of Operator Response to Landowner Issues:**

**Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**

**Facility**

Facility ID: 216488 Type: WELL API Number: 067-08094 Status: PR Insp. Status: EI

**Producing Well**

**Comment:** \_\_\_\_\_

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Inspector Name: Hughes, Jim

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

**Cropland**

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

**Non-Cropland**

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Inspector Name: Hughes, Jim

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment                                      |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|--|
| Ditches          | Pass            | Ditches                 | Pass                  | MHSP          | Pass                     | Chemical container in secondary containment. |
|                  |                 | Culverts                | Pass                  |               |                          |  |

S/A/V: SATISFACTOR

Corrective Date: \_\_\_\_\_

Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                  | URL   |
|--------------|------------------------------|---|
| 674900104    | Unlabeled PBV                | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3404359">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3404359</a> |
| 674900105    | Stairway off of its mooring. | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3404360">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3404360</a> |