

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
08/07/2014

Document Number:
673705343

Overall Inspection:

ACTION REQUIRED

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>238071</u>	<u>317320</u>	<u>Sherman, Susan</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>81720</u>
Name of Operator:	<u>STANDLEY* ROBERT K DBA OTIS ENERGY</u>
Address:	<u>327 S VINE ST</u>
City:	<u>OTIS</u> State: <u>CO</u> Zip: <u>80743-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Standley, Robert	(970) 246-3439	standleyent@msn.com	

Compliance Summary:

QtrQtr: SWSE Sec: 13 Twp: 2N Range: 49W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/27/2014	670600256			VIOLATION			Yes
07/07/2008	200192539	PR	PR	ACTION REQUIRED			Yes
10/02/2007	200120851	PR	PR	SATISFACTOR Y			No
09/06/2006	200097740	PR	PR	ACTION REQUIRED		Fail	Yes
04/26/2001	200017072	PR	PR	ACTION REQUIRED	I	Pass	Yes
09/22/1997	500160116	PR	SI			Pass	No
02/26/1997	500160115	DG	WO			Pass	No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238071	WELL	PR	12/28/2010	OG	121-10574	GEOGLEIN 5	PR <input checked="" type="checkbox"/>

Equipment:

Location Inventory

--

Inspector Name: Sherman, Susan

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	ACTION REQUIRED	Rills in road to location.	Install stormwater BMPs to prevent erosion and transport of sediment.	10/13/2014

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY			
TANK LABELS/PLACARDS	ACTION REQUIRED		Install sign to comply with rule 210.	10/13/2014
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WEEDS	ACTION REQUIRED	See attached photo.	Control weeds at battery (see attached photos).	10/13/2014
UNUSED EQUIPMENT	ACTION REQUIRED		Remove unused equipment.	10/13/2014

Spills:

Type	Area	Volume	Corrective action	CA Date
Crude Oil	WELLHEAD	<= 5 bbls	Remove or remediate stained soil at wellhead (see attached photo). Fix leak.	08/29/2014

Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 238071

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 238071 Type: WELL API Number: 121-10574 Status: PR Insp. Status: PR

Producing Well

Comment: **Apr 2013 last reported production data.**
"Each producer or operator of an oil or gas well shall file with the Commission, within forty-five (45) days after the month in which production occurs, a report on Operator's Monthly Production Report, Form 7, containing all information required by said form."

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS: _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment: sugarbeet field

1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland
 Top soil replaced _____ Recontoured _____ Perennial forage re-established _____
Non-Cropland

Inspector Name: Sherman, Susan

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			

S/A/V: **ACTION REQUIRED** Corrective Date: **10/13/2014**

Comment: _____

CA: **Install stormwater BMPs to prevent site degradation.**

Pits: NO SURFACE INDICATION OF PIT

Pit Type: Produced Water Lined: NO Pit ID: _____ Lat: _____ Long: _____

Lining:
 Liner Type: _____ Liner Condition: _____
 Comment: _____

Fencing:
 Fencing Type: _____ Fencing Condition: _____
 Comment: _____

Netting:
 Netting Type: _____ Netting Condition: _____
 Comment: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____
 Pit (S/A/V): SATISFACTOR Comment: West pit. Weeds on banks.
 Corrective Action: Date: _____

Pit Type: Produced Water Lined: NO Pit ID: _____ Lat: _____ Long: _____

Lining:
 Liner Type: _____ Liner Condition: _____
 Comment: _____

Fencing:
 Fencing Type: _____ Fencing Condition: _____
 Comment: _____

Netting:
 Netting Type: _____ Netting Condition: _____
 Comment: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____
 Pit (S/A/V): SATISFACTOR Comment: East pit. Weeds on banks.
 Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
Corrective actions from 3/27/2014 inspection that are not noted as completed on this inspection are still required to be completed in addition to corrective actions on this inspection.	ShermaSe	08/14/2014

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673705405	Standley Geoglein 5 well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3409972
673705406	Standley Geoglein 5 wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3409973
673705407	Standley Geoglein 5 wellhead2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3409974
673705408	Standley Geoglein 5 well equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3409975
673705409	Standley Geoglein 5 well IR	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3409976

673705410	Standley Geoglein 5 well BH	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3409977
673705411	Standley Geoglein 5 well BH2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3409978
673705412	Standley Geoglein 5 Bat sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3409979
673705413	Standley Geoglein 5 Bat tanks	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3409980
673705414	Standley Geoglein 5 Bat tanks	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3409981
673705415	Standley Geoglein 5 Bat treaters	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3409982
673705416	Standley Geoglein 5 Bat weeds	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3409983