

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
08/15/2014

Document Number:
674600791

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>215411</u>	<u>333612</u>	<u>Maclaren, Joe</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10000</u>
Name of Operator:	<u>BP AMERICA PRODUCTION COMPANY</u>
Address:	<u>501 WESTLAKE PARK BLVD</u>
City:	<u>HOUSTON TX</u> Zip: <u>77079</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Chuck		chuck.browning@state.co.us	
Campbell, Patti	970-335-3828	patricia.campbell@bp.com	Regulatory Analyst
Koehler, Bob		bob.koehler@state.co.us	

Compliance Summary:

QtrQtr: <u>SWNW</u>		Sec: <u>15</u>		Twp: <u>34N</u>		Range: <u>7W</u>	
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/15/2013	663401100			SATISFACTORY Y			No
08/06/2012	669400012	IJ	AC	SATISFACTORY Y			No
08/16/2011	200318427	MI	AC	SATISFACTORY Y			No
08/16/2011	200318539	MI	AC	SATISFACTORY Y			No
08/11/2010	200266440	RT	AC	SATISFACTORY Y			No
06/25/2009	200213439	RT	AC	SATISFACTORY Y			No
08/22/2008	200194632	RT	AC	SATISFACTORY Y			No
08/09/2007	200116515	RT	AC	ACTION REQUIRED			Yes
08/14/2006	200095373	MI	AC	SATISFACTORY Y		Pass	No
07/19/2005	200075437	RT	AC	SATISFACTORY Y		Pass	No
08/13/2004	200058920	RT	AC	SATISFACTORY Y		Pass	No
07/31/2003	200042956	RT	AC	SATISFACTORY Y		Pass	No
08/08/2002	200029531	SR	WO	SATISFACTORY Y		Pass	No

Inspector Name: Maclaren, Joe

09/12/2001	200020165	MI	AC	SATISFACTOR Y		Pass	No
07/19/2001	200020137	MI	AC	SATISFACTOR Y		Pass	No
02/14/2001	200020144	MI	AC	SATISFACTOR Y		Pass	No
12/12/2000	200013059	CA	WO	SATISFACTOR Y		Pass	No
12/08/2000	200013058	CA	WO	SATISFACTOR Y		Pass	No
08/25/2000	200009596	RT	AC	SATISFACTOR Y		Pass	No
05/11/1999	500149065	BH	PR			Pass	No
12/15/1997	500149064						

Inspector Comment:

This report is for a UIC Routine (Annual) inspection only for the Sitton Disposal #1 (API 067-07016).

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150250	UIC DISPOSAL	CL	03/03/1989		-	SITTON DISPOSAL 1	CL
159068	UIC DISPOSAL	AC	09/13/2001		-	SITTON DISPOSAL 1	AC
159077	UIC DISPOSAL	AC	09/13/2001		-	SITTON WATER DISPOSAL #2	AC
215411	WELL	IJ	08/29/2001	DSPW	067-07016	SITTON DISPOSAL 1	IJ
261961	WELL	IJ	10/08/2012	DSPW	067-08669	SITTON WATER DISPOSAL 2	IJ

Equipment:

Location Inventory

Special Purpose Pits: _____ Drilling Pits: _____ Wells: _____ Production Pits: _____
 Condensate Tanks: _____ Water Tanks: _____ Separators: _____ Electric Motors: _____
 Gas or Diesel Mortors: _____ Cavity Pumps: _____ LACT Unit: _____ Pump Jacks: _____
 Electric Generators: _____ Gas Pipeline: _____ Oil Pipeline: _____ Water Pipeline: _____
 Gas Compressors: _____ VOC Combustor: _____ Oil Tanks: _____ Dehydrator Units: _____
 Multi-Well Pits: _____ Pigging Station: _____ Flare: _____ Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 215411

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 159068 Type: UIC API Number: - Status: AC Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: 1600

UIC Routine

Inj./Tube: Pressure or inches of Hg 600 psi Previous Test Pressure _____ MPP _____
(e.g. 30 psig or -30" Hg) Inj Zone: _____

TC: Pressure or inches of Hg 0 psi Previous Test Pressure _____ Last MIT: _____

Brhd: Pressure or inches of Hg 5 psi Previous Test Pressure _____ AnnMTRReq: NO

Comment: No gas movement at all when the casing was opened up. Slight vacume on casing while opened. Bradenhead blew down in 5 seconds time to 0 psi. Active injection at time of inspection with one pump running. Preparing to do an acid job on this well.

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat Long

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____

Waste Material Onsite? _____ CM _____
CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT