

Inspector Name: DURAN, JOHN

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

08/18/2014

Document Number:

668002463

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | |
|---------------------|---------------|---------------|--------------------|--|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection |
| | <u>258571</u> | <u>333909</u> | <u>DURAN, JOHN</u> | <input type="checkbox"/> 2A Doc Num: _____ |

Operator Information:OGCC Operator Number: 100264 Name of Operator: XTO ENERGY INCAddress: 382 CR 3100City: AZTECState: NMZip: 87410**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|---------------------------|-------------------------------|-----------------------------|
| Trujillo, Irwin | 719-846-0272/719-859-2264 | irwin_trujillo@xtoenergy.com | Sr. Env. Tech., Raton Basin |
| Jaramillo, Diane | 505-333-3109 | diane_jaramillo@xtoenergy.com | Eng. Mngr - Reg., Aztec, NM |
| Harrison, Lyndon | 505-333-3100 | Lyndon_Harrison@xtoenergy.com | |

Compliance Summary:QtrQtr: SWSW Sec: 34 Twp: 34S Range: 67W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 11/22/2011 | 659400062 | PR | PR | S | | | N |
| 03/11/2008 | 200128352 | PR | PR | S | | | N |
| 03/04/2005 | 200067859 | PR | PR | S | | P | N |
| 07/09/2002 | 200028753 | PR | PR | S | | P | N |
| 09/25/2001 | 1067144 | PR | PR | S | | P | N |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------------------------------|
| 258571 | WELL | PR | 03/13/2001 | GW | 071-07106 | HILL RANCH 34-13 V | <input checked="" type="checkbox"/> |
| 258752 | WELL | PR | 12/01/2010 | GW | 071-07141 | HILL RANCH 34-13R | <input checked="" type="checkbox"/> |
| 268840 | PIT | | 07/28/2003 | | - | HILL RANCH 34-13V | <input type="checkbox"/> |
| 292657 | PIT | AC | 10/04/2008 | | - | HILL RANCH 34-13R | <input type="checkbox"/> |

Equipment:Location Inventory

Inspector Name: DURAN, JOHN

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Signs/Marker:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------|-----------------------------|---------|-------------------|---------|
| WELLHEAD | Satisfactory | | | |

Emergency Contact Number: (S/U/V) Satisfactory _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Fencing:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|-----------|-----------------------------|---------|-------------------|---------|
| PUMP JACK | Satisfactory | | | |

Equipment:

| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|--------------------|---|-----------------------------|---------|-------------------|---------|
| Vertical Separator | 2 | Satisfactory | | | |
| Pump Jack | 1 | Satisfactory | | | |
| Deadman # & Marked | 5 | Satisfactory | | | |
| Gas Meter Run | 2 | Satisfactory | | | |
| Progressive Cavity | 1 | Satisfactory | | | |

Venting:

| Yes/No | Comment |
|--------|---------|
| | |

Flaring:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|------|-----------------------------|---------|-------------------|---------|
| | | | | |

Predrill

Location ID: 258571

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:****Comment:****Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 258571 Type: WELL API Number: 071-07106 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 258752 Type: WELL API Number: 071-07141 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: DURAN, JOHN

| | | | |
|---|--|------------------------------|------------|
| Comment: <input style="width:700px" type="text"/> | | | |
| Corrective Action: _____ | | Date: _____ | |
| Reportable: _____ | GPS: Lat _____ | Long _____ | |
| Proximity to Surface Water: _____ | | Depth to Ground Water: _____ | |
| Water Well: | | | |
| | | Lat _____ | Long _____ |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ | |
| Field Parameters: | | | |
| <input style="width:300px" type="text"/> | | | |
| Sample Location: <input style="width:400px" type="text"/> | | | |
| Emission Control Burner (ECB): _____ | | | |
| Comment: _____ | | | |
| Pilot: _____ | Wildlife Protection Devices (fired vessels): _____ | | |

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment:

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Inspector Name: DURAN, JOHN

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____

Pits:

Inspector Name: DURAN, JOHN

Pit Type: Produced Water Lined: NO Pit ID: _____ Lat: _____ Long: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____

Pit (S/U/V): Satisfactory Comment: 30' x 90', shared, L-shaped.

Corrective Action: _____ Date: _____

| | | | |
|---------|-------------|------------|-----------------|
| Permit: | Facility ID | Permit Num | Expiration Date |
| | 268840 | 1121951 | |
| | 292657 | 2059169 | |