

<b>FORM INSP</b> <small>Rev 05/11</small>	<b>State of Colorado</b> <b>Oil and Gas Conservation Commission</b> <small>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109</small>		DE	ET	OE	ES
--	---	--	----	----	----	----

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
	285117	306078	JOHNSON, RANDELL		

Inspection Date: 08/19/2014

Document Number: 668302213

Overall Inspection: **Unsatisfactory**

**Operator Information:**

OGCC Operator Number: 47120 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Contact Information:**

Contact Name	Phone	Email	Comment
Kilcrease, Keith	970-506-5926	keith.kilcrease@anadarko.com	Production Superintendent
Avant, Paul	O:720-929-6457, C:720-273-2688	paul.avant@anadarko.com	Rockies Regulatory Affairs
Anadarko, KerrMcGee		cogccinspections@anadarko.com	Kerr McGee
Cocciolone, Ashley	720-929-6625	ashley.cocciolone@anadarko.com	Regulatory Supervisor

**Compliance Summary:**

QtrQtr: SESE Sec: 27 Twp: 2N Range: 67W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/25/2009	200206043	PR	PR	S			N

**Inspector Comment:**

---

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
285117	WELL	PR	11/21/2006	OW	123-23957	SEVCIK V 27-23	<input checked="" type="checkbox"/>

**Equipment:** Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			

TANK LABELS/PLACARDS	Satisfactory			
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

**Fencing/:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK BATTERY	Satisfactory	Twisted wire fencing		
SEPARATOR	Satisfactory	Twisted wire fencing		
WELLHEAD	Satisfactory	Pipe and rod fencing		

**Equipment:**

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Plunger Lift	1	Satisfactory			
Emission Control Device	1	Satisfactory			
Gas Meter Run	1	Satisfactory	Pipeline meter and metal meter run house		
Horizontal Heated Separator	1	Satisfactory			
Gas Meter Run	1	Satisfactory	Operator check meter on outlet of separator		

**Facilities:**  New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
OTHER	1	OTHER	Open Top	40.105496,-104.871812

S/U/V: **Unsatisfactory** Comment: Contents and capacity unknown - no signage

Corrective Action: Provide required contents, capacity and NFPA signage for workover/blowdown tank on workover location Corrective Date: 08/26/2014

**Paint**

Condition \_\_\_\_\_

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
	Inadequate	Walls Insufficient	Base Insufficient	Inadequate

Corrective Action: Provide secondary containment for workover/blowdown tanks on workover locations Corrective Date: 08/26/2014

Comment: Workover/blowdown tank on location did not have the required secondary containment

<b>Facilities:</b>		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	1	<100 BBLS	BV CONCRETE	40.104700,-104.870090	
S/U/V:	Satisfactory		Comment:	53 bbls	
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition					
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					

<b>Facilities:</b>		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
CRUDE OIL	2	OTHER	STEEL AST	40.104700,-104.870090	
S/U/V:	Satisfactory		Comment:	268 bbls	
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					

<b>Venting:</b>	
Yes/No	Comment
NO	

<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 285117

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 285117 Type: WELL API Number: 123-23957 Status: PR Insp. Status: WK

**Workover**

**Comment:** Workover rig over the hole in the process of setting a packer on the end of the tubing, testing the tubing and upgrading wellhead from 2000 pound rating to 5000 pound rating in an attempt to mitigate interference from adjacent high pressure fracs.

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
**Comment:** \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_  
Comment: \_\_\_\_\_  
Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment:

Overall Interim Reclamation  In Process

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment:

Corrective Action:  Date \_\_\_\_\_

Overall Final Reclamation  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			
Other	Pass	Other	Pass			Vegetation

S/U/V: Satisfactory Corrective Date: \_\_\_\_\_

Comment:

CA: