

Site Photos (05-009-06570) 8/20/2014

Walking in towards the west looking at the disturbed location in the cultivated field.



Looking north at center of location.



Site Photos (05-009-06570) 8/20/2014

Looking east at center of location.



Looking south at center of location.



Site Photos (05-009-06570) 8/20/2014

Looking west at center of location.



Metal and plastic pipe debris.



Site Photos (05-009-06570) 8/20/2014

Disturbance Area.



Surrounding crop.

