

Site Photos (05-009-06271) 8/20/2014

Center of location looking North.



Center of location looking West.



Site Photos (05-009-06271) 8/20/2014

Center of location looking South.



Center of location looking East.



Site Photos (05-009-06271) 8/20/2014

Water coming to the surface on location. May be possible gas leak. Operator was contacted.



Standing on west side of location looking east at location.



Site Photos (05-009-06271) 8/20/2014

Soils were very compacted and was unable to break through the surface with shovel.



Surrounding field containing evidence of previous crop growth .

