

Site Photos (05-009-06099) 8/20/2014

Access road onto location was never recontoured.



Looking East at location from access road.



Site Photos (05-009-06099) 8/20/2014

Onsite Transect Northeast



Onsite Transect Ground Cover



Site Photos (05-009-06099) 8/20/2014

Onsite Transect Northwest



Onsite Transect Southeast



Site Photos (05-009-06099) 8/20/2014

Onsite Transect Southwest



Offsite Transect West



Site Photos (05-009-06099) 8/20/2014

Offsite Transect Groundcover



Offsite transect South



Site Photos (05-009-06099) 8/20/2014

Offsite transect North



Offsite transect East



Site Photos (05-009-06099) 8/20/2014

East side of location looking West.



Trash debris still remained on location.



Site Photos (05-009-06099) 8/20/2014

Three bare areas measured to be 15'x15' each.



Field bindweed growing on location.

