

Session Report

8/27/2014

Calibration History

<u>Date</u>	<u>Calibration Action</u>	<u>Level</u>	<u>Cal. Model Type</u>	<u>Serial Number</u>	<u>Cert. Due Date</u>
8/27/2014 5:36:08 AM	Calibration	114.0			
8/27/2014 7:10:58 AM	Verification	114.0			

Information Panel

Name	Encana - Vogl-Geist-McCoy Frac Location (433787)
Start Time	8/27/2014 5:39:46 AM
Stop Time	8/27/2014 7:07:51 AM
Device Name	BGN010009
Model Type	SoundPro DL
Device Firmware Rev	R.13F
Comments	Sound survey was taken (in response to Complaint Report #200411245) approximately 25 feet south of complainant's house at Lat. 40.16266, Long. -104.94238. Nearest sound source (Encana western frac location) was 1.13 miles northeast of complainant's house at Lat. 40.16811, Long. -104.91502 - see snip-it of aerial view attached to Inspection Document #668302267. Fracking began first at 5:45 am on the nearest western location, and fracking began on the adjacent eastern location (0.39 miles/2,065 ft. farther east - see snip-it or aerial view attached to Inspection Document #668302267) at 6:00 am.

Logged Data Chart

Encana - Vogl-Geist-McCoy Frac Location (433787): Logged Data Chart

