



Photo 1. View from southeastern corner of project area toward center. Note dense grass revegetation in foreground.



Photo 2. View from southwestern corner of project area toward center. Note abundant cheatgrass (*Bromus tectorum*) and lack of desirable plant species in foreground.



Photo 3. View of vegetated, erosive-channel on eastern edge of well pad facing eastward.