


Site Photos (05-061-06233) 8/26/2014

Pipe riser on location showing weed growth (Russian thistle) around equipment.



Pipe riser on location showing weed growth (Russian thistle) around equipment.



Site Photos (05-061-06233) 8/26/2014

Trash debris left on location..



Very little crop growth on location.

