

Site Photos (05-061-06155) 8/26/2014

Looking South from center of location.



Looking East from center of location.



Site Photos (05-061-06155) 8/26/2014

Looking North from center of location.



Looking West from center of location.



Site Photos (05-061-06155) 8/26/2014

Waddles still remain.



Bare area of vegetation was approx. 100'x 70'. Several other bare areas were noticed on location.



Site Photos (05-061-06155) 8/26/2014

Surrounding vegetation (reference area)



Access road is well vegetated.

