

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
09/02/2014

Document Number:
674600875

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>215236</u>	<u>325691</u>	<u>Maclaren, Joe</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10000</u>
Name of Operator:	<u>BP AMERICA PRODUCTION COMPANY</u>
Address:	<u>501 WESTLAKE PARK BLVD</u>
City:	<u>HOUSTON</u> State: <u>TX</u> Zip: <u>77079</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Campbell, Patti	970-335-3828	patricia.campbell@bp.com	Regulatory Analyst

Compliance Summary:

QtrQtr: NWNW Sec: 35 Twp: 34N Range: 9W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/28/2010	200246805	PR	PR	SATISFACTORY			No
05/09/2007	200120463	PR	PR	SATISFACTORY			No
08/25/2005	200078023	PR	PR	SATISFACTORY		Pass	No
07/27/2004	200060921	PR	PR	SATISFACTORY		Pass	No
07/22/2003	200043575	PR	PR	SATISFACTORY		Pass	No
05/14/2002	200027773	PR	PR	SATISFACTORY		Pass	No
02/02/2001	200015123	PR	PR	SATISFACTORY		Pass	No
02/02/2001	200015124	ID	SI	SATISFACTORY		Pass	No
11/03/1999	200002457	ID	SI	SATISFACTORY		Pass	No
09/29/1997	500148696	ID	SI	SATISFACTORY		Pass	No
09/23/1996	500148695	PR	PR	SATISFACTORY		Pass	No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
215236	WELL	PR	12/31/2001	GW	067-06841	TURNER SECURITIES A 1	PR	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

--

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
STORAGE OF SUPL		Landowner storing cars/ equipment on west side well pad.		
TRASH		Landowner trash being dumped off south/ east sides of well pad.	Install "no dumping" signs/ discourage future dumping from well pad.	

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
OTHER	SATISFACTORY	Stock panels around all equipment.		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Ancillary equipment	1	SATISFACTORY	Hydraulic Power Unit		
Ancillary equipment	1	SATISFACTORY	Telemetry Equipment		
Ancillary equipment	1	SATISFACTORY	Water Transfer Equipment		
Other	1	SATISFACTORY	Flowing wellhead		
Bird Protectors	3	SATISFACTORY			
Deadman # & Marked	4	SATISFACTORY			
Gas Meter Run	1	SATISFACTORY			
Ancillary equipment	1	SATISFACTORY	Gas/ water line risers with valves		
Ancillary equipment	1	SATISFACTORY	Chemical Injection System		
Vertical Heated Separator	1	SATISFACTORY			

Inspector Name: Maclaren, Joe

Flow Line	1	SATISFACTORY		
Pig Station	1	SATISFACTORY		

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST	37.154120,-107.801540

S/AV: SATISFACTORY Comment: (1) 300 bbl produced water tank painted still has primer coat/ white. Tank in need of painting.

Corrective Action: _____ Corrective Date: _____

Paint

Condition _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action _____ Corrective Date _____

Comment _____

Venting:

Yes/No _____ Comment _____

NO _____

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 215236

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 215236 Type: WELL API Number: 067-06841 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? Pass CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ I _____

Inspector Name: Maclaren, Joe

Comment:

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

S/A/V: SATISFACTOR _____ Corrective Date: _____

Y

Comment:

CA:

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674600882	Unpainted tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3423147
674600883	Trash on side of well pad.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3423148