

Site Photos (05-061-06366) 8/26/2014

Looking South at location from the access road to the North.




Looking back at the access road to the Northwest.





Site Photos (05-061-06366) 8/26/2014

Onsite Transect South



Onsite Transect Ground Cover





Site Photos (05-061-06366) 8/26/2014

Onsite Transect East



Onsite Transect West






Site Photos (05-061-06366) 8/26/2014

Onsite Transect North



Offsite Transect East





Site Photos (05-061-06366) 8/26/2014

Offsite Transect Groundcover



Offsite transect North





Site Photos (05-061-06366) 8/26/2014

Offsite transect South



Offsite transect West

