

Site Photos (05-061-06576) 8/27/2014

Looking at location from the Southwest corner.



Looking at access road toward the Southwest from the location.




Site Photos (05-061-06576) 8/27/2014

Weed growth on location and access road (Russian thistle)



Onsite Transect Northeast



Site Photos (05-061-06576) 8/27/2014

Onsite Transect Ground Cover



Onsite Transect Northwest



Site Photos (05-061-06576) 8/27/2014

Onsite Transect Southeast




Onsite Transect Southwest



Site Photos (05-061-06576) 8/27/2014

Offsite Transect Southwest



Offsite transect Southeast



Site Photos (05-061-06576) 8/27/2014

Offsite transect Northwest



Offsite transect Northeast

