

Site Photos (05-061-06296) 8/26/2014

Frazee 1-6 location API# 05-061-06296



Oil stained soil at wellhead



Site Photos (05-061-06296) 8/26/2014

Holes in containment berms



Fence is down and vegetation growth inside berms is a potential fire hazard



Site Photos (05-061-06296) 8/26/2014

Access road is eroded and road has been created around it



Erosion along access road

