

Reference Area Photographs

Inspection Conducted on August 13, 2014

**Linn Energy
Chevron J20 596 Pad
Location ID #335841
Pit Facility ID #423848**

Chevron J20 596 Pad



Signs at the entrance



Tanks with secondary containment. Lined, clean.

Chevron J20 596 Pad



Pit Facility ID # 423848. Pit empty. Liner removed. Bottom of pit has been excavated and material extended in site for landfarming. No signs of staining in the pit.



Another view of the pit.

Chevron J20 596 Pad



Material from the pit extended for landfarming. Located on the edge of the pad. Pieces of liner mixed with the soil.



Berm around the landfarm operation.