



Photo 1. View from southwestern corner of well pad facing center.




Photo 2. View of beginning of vegetation transect within interim reclamation area of the well pad area facing westward.





Photo 3. Birdseye view of revegetation at midpoint of vegetation transect within the interim reclamation area of the well pad. Vegetation is field bindweed.