



Photo 1. View of Russian knapweed (green with tan flowerheads) growing along the eastern edge of the project area.



Photo 2. View from northwestern corner of well pad facing center. It appears that sediment in the foreground has eroded from adjacent (north and west) slopes.





Photo 3. View of western edge of the well pad. It appears that sediment is eroding from adjacent slopes.



Photo 4. View from northeastern corner of the well pad facing center.