

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:
09/22/2014Document Number:
673706458

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	238025	317310	Sherman, Susan	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 66565Name of Operator: P & M PETROLEUM MANAGEMENT LLC

Address: _____

City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Neibauer, Ed	(303) 842-5551	pmpetroleum4@msn.com	
Ikenouye, Teri	(303) 894-2100	teri.ikenouye@state.co.us	COGCC Production/Data Support
Ash, Margaret	(303) 894-2100	margaret.ash@state.co.us	COGCC Field Inspection Manager

Compliance Summary:QtrQtr: NWNW Sec: 30 Twp: 2S Range: 49W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/13/2011	200321080	ES	PR	ACTION REQUIRED			Yes
10/27/2010	200281283	PR	PR	ACTION REQUIRED			Yes
04/16/2007	200110225	PR	PR	ACTION REQUIRED		Fail	Yes
01/29/2002	200023483	PR	PR	SATISFACTORY	P	Pass	No
09/28/1994	500160011		ND				

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
238025	WELL	SI	07/19/2013	GW	121-10528	AXSOM 430	SI	<input checked="" type="checkbox"/>
423438	PIT	AC	06/02/2011		-	AXSOM 4-30	AC	<input type="checkbox"/>
425796	PIT	AC	10/06/2011		-	AXSOM 4-30	AC	<input type="checkbox"/>

Equipment:Location Inventory

Inspector Name: Sherman, Susan

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	ACTION REQUIRED	Road access limited. Wind blown sand and weeds need maintenance.	Maintain access road.	10/31/2014

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	ACTION REQUIRED	Separator requires NFPA diamond label.	Install sign to comply with rule 210.	10/31/2014
WELLHEAD	SATISFACTORY			
CONTAINERS	SATISFACTORY	chemical container		

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WEEDS	ACTION REQUIRED	See attached photo.	Control weeds.	10/31/2014

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
LOCATION	SATISFACTORY	Barbed wire.		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Vertical Separator	1	ACTION REQUIRED	Concrete pad. No label.	Install NFPA diamond label.	10/31/2014
Ancillary equipment	1	ACTION REQUIRED	No secondary containment (see attached photo).	See stormwater section for CA.	10/31/2014
Gas Meter Run	1	SATISFACTORY			

Inspector Name: Sherman, Susan

Plunger Lift	1	SATISFACTORY			
--------------	---	--------------	--	--	--

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 238025

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 238025 Type: WELL API Number: 121-10528 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In☐ Temporarily Abandoned

Reminder: _____

S/A/V: _____

CA Date: _____

CA: _____

Comment: SI since Apr 2013-last reported production records. MIT will be required on 4/1/2015.

Tubing pressure 50 psi per existing gauge.

309. COGCC Form 7. OPERATOR'S MONTHLY PRODUCTION REPORT

Each producer or operator of an oil or gas well shall file with the Commission, within forty-five (45) days after the month in which production occurs, a report on Operator's Monthly Production Report, Form 7, containing all information required by said form. In addition, all fluids produced during the initial testing and completion shall be reported on Operator's Monthly Production Report, Form 7 within forty-five (45) days after the month in which testing and completion occurs.

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: rangeland

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? In

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation In

1003 f. Weeds Noxious weeds? I

Comment: _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Fail	MHSP	Fail	

Inspector Name: Sherman, Susan

S/A/V: **ACTION
REQUIRED**

Corrective Date: **11/07/2014**

Comment: **Chemical container requires secondary containment. See Road Section for road compaction CA.**

CA: **Install stormwater BMP to prevent site degradation.**

Pits: ☐ NO SURFACE INDICATION OF PIT

Pit Type: Produced Water Lined: NO Pit ID: _____ Lat: 39.856090 Long: -102.912050

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____

Pit (S/A/V): SATISFACTOR Comment: **dry**

Corrective Action: _____

Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	423438	2214221	
	425796	2216437	
	425796	2216437	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673706459	P&M Petroleum Management Axom 430 well sign E	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3440731
673706460	P&M Petroleum Management Axom 430 wellhead E	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3440732
673706461	P&M Petroleum Management Axom 430 separator E	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3440733
673706462	P&M Petroleum Management Axom 430 well gauges	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3440734
673706463	P&M Petroleum Management Axom 430 well gauge	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3440735
673706464	P&M Petroleum Management Axom 430 well pit N	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3440736
673706465	P&M Petroleum Management Axom 430 separator W	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3440737

673706466	P&M Petroleum Management Axom 430 well weeds E	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3440738
673706467	P&M Petroleum Management Axom 430 separator pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3440739
673706468	P&M Petroleum Management Axom 430 separator pad 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3440740

ACTION REQUIRED

ANY ACTION REQUIRED items listed on this report indicate that the oil and gas facility or the oil and gas operations listed on the report may be in violation of the rules and regulations of the Colorado Oil and Conservation Commission (“COGCC”) and corrective action is required.

There is reasonable cause to believe that a violation of the Oil and Gas Conservation Act, or of any rule, regulation, or order of the Commission, or of any permit issued by the Commission, has occurred. The Operator’s compliance with this Inspection Report is required to resolve these alleged violations. This document requires the Operator to timely respond to the COGCC and to comply with directives as listed by the **Corrective Action Deadline Date**. Failure to do so will result in the issuance of a Notice of Alleged Violation and initiation of enforcement proceedings in which COGCC will seek monetary penalties for the alleged violations pursuant to § 34-60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1. (Please note that the COGCC's penalty authority was recently increased to a maximum of \$15,000 per day and penalties are no longer capped at a maximum of \$10,000 per violation.)