Cover Data

Date: 9/17/2014 Inspected By: Ryan Costa

Location: 055-06153

Transect #/disturbed/Ref	Disturbed		Reference					
Transect Orientation and first photo, degrees	37.57057 -104.85502	NW	37.56500 -104.85195	N				
Photo Midpoint (2)	Groundcover	SW, NE	Groundcover	E, W				
End transect	37.57075 -104.85530	SE	37.56525 -104.85201	S				
Photo other								
Photo other								
Aspect/Slope								
	1st Hit	2nd	1st Hit	2nd	1st Hit	2nd	1st Hit	2nd
Litter	⊠⊠:.	23%	⊠⊠⊠:	32%				
Bare Soil	⊠⊠⊠⊠⊠:1	55%	⊠⊠J	27%				
Rock								
Total Weeds		16%		—				
Total Desirable Species		6%		41%				
80% Check	15%		100%					
Species								
Blue Flax	..	2%						
Russian thistle	⊠.J	16%						
Western wheat grass	..	3%	.	1%				
Blue Grama	.	1%	⊠⊠⊠:.	33%				
Broomsnakeweed			:.	3%				
Rubber rabitbrush			.	1%				
Prairie Sandreed			:	2%				
Prickly pear cactus			.	1%				