

Site Photos (05-055-06154) 9/17/2014

Looking North from center of location



Looking West from center of location



Site Photos (05-055-06154) 9/17/2014

Looking South from center of location




Looking East from center of location



Site Photos (05-055-06154) 9/17/2014

Onsite Transect Northeast



Onsite Transect Ground Cover



Site Photos (05-055-06154) 9/17/2014

Onsite Transect Northwest



Onsite Transect Southeast



Site Photos (05-055-06154) 9/17/2014

Onsite Transect Southwest



Offsite Transect North



Site Photos (05-055-06154) 9/17/2014

Offsite Transect Groundcover



Offsite transect West



Site Photos (05-055-06154) 9/17/2014

Offsite transect East



Weeds on location: Scotch thistle

