

Battlement Mesa 34-F

Inspection# 675200585

Remove hose that is directed at  
drainage.



Remove hose that is directed at  
drainage.



Subsidence on cut slope.

