

STATE OF
COLORADO

EnviroScan - DNR, OGCC <dnr_ogcc.enviroscan@state.co.us>

Franklin Stermole Unit 1 (API #123-09052) Inspection Doc #668302299

2 messages

Axelson - DNR, John <john.axelson@state.co.us>

Mon, Sep 22, 2014 at 12:09 PM

To: Susana Lara-Mesa <slaramesa@kpk.com>

Cc: Randell Johnson - DNR <Randell.Johnson@state.co.us>, OGCC EnviroScan - DNR
<OGCC.EnviroScan@state.co.us>

Hi Susi,

Randell Johnson inspected the subject location in response to a complaint (Doc #200411312) on September 3, 2014. You were copied on the inspection, and it is attached again for reference.

There were a few things that fell under the environmental unit including removal of oily waste and the unused concrete produced water vault. Please note that the concrete vault removal requires prior approval of a Form 27 in accordance with Rule 905. You can also document removal of the site wide oily waste using that same Form 27.

Please let me know if you have any questions regarding those corrective actions and the corresponding completion deadlines.

Thank you,
John

John E. Axelson, P.G.
East Environmental Supervisor



P 303.894.2100 x5115 | F 303.894.2109 | C 303-916-0527

1120 Lincoln Street, Suite 801, Denver, CO 80203

john.axelson@state.co.us | www.colorado.gov/cogcc

Cc. Complaint #200411312 - Correspondence to Operator

**AWC Complaint_insp_668302299.pdf**

129K

Susana Lara-Mesa <SLaraMesa@kpk.com>

Mon, Sep 22, 2014 at 1:38 PM

To: "Axelson - DNR, John" <john.axelson@state.co.us>

Cc: Randell Johnson - DNR <Randell.Johnson@state.co.us>, OGCC EnviroScan - DNR
<OGCC.EnviroScan@state.co.us>

John,

We've had Surface owner issues and only had access to clean up the weeds. Our land department is working on being able to get large equipment to work on these issues. I will file a Form 27 as soon as we have access granted.

Thanks,

Susi

Susana Lara-Mesa | K.P. Kauffman Company, Inc.

1675 Broadway, Suite 2800 | Denver, CO 80202 | T: (303) 825-4822 | SLaraMesa@kpk.com | www.kpk.com

From: Axelson - DNR, John [mailto:john.axelson@state.co.us]

Sent: Monday, September 22, 2014 12:09 PM

To: Susana Lara-Mesa

Cc: Randell Johnson - DNR; OGCC EnviroScan - DNR

Subject: Franklin Stermole Unit 1 (API #123-09052) Inspection Doc #668302299

[Quoted text hidden]