



Photo 1. View from southeastern corner of well pad toward center. Vegetation is largely redroot pigweed and Russian thistle.





Photo 2. View of eastern edge of well pad with grassy pasture off of well pad, on left ,and weedy vegetation on well pad, on right.



Photo 3. View from northwestern corner of well pad toward center. Revegetation on western side of interim reclamation area is largely wheat and sunflower.





Photo 4. View of failed straw wattle on northern side of access road, downstream of well pad and rock check dams.



Photo 5. View of sediment discharge onto the well pad adjacent to the access road at the entrance to the well pad.