



Photo 1. View from southwestern edge of well pad facing center.



Photo 2. View of planted tree within the western portion of the interim reclamation area.



Photo 3. View of vegetated water diversion ditch within western portion of interim reclamation area.



Photo 4. View of vegetated swale and silt trap within western portion of interim reclamation area.