



Photo 1. View of dense population of Russian thistle plants within an unused portion of the working area. These plants need to be removed from the location and disposed of properly.



Photo 2. View of Russian thistle plants (in background) within the western portion of the interim reclamation area. These plants need to be removed and disposed of properly.



Photo 3. View of area with mud and weedy vegetation within unused portion of working area that needs to be revegetated.



Photo 4. View of cobble on soil surface within unused portion of the center of the working area. It may be necessary to remove cobble and incorporate topsoil to revegetate this area.