



Photo 1. View of Scotch thistle population within the southern portion of the interim reclamation area.





Photo 2. View of Scotch thistle just outside of the fencing on the eastern edge of the well pad that appear to be expanding from source population within the project area.





Photo 3. View of rig cable within the interim reclamation area that needs to be removed.





Photo 4. View of dense population of Russian thistle plants (orange tinted) growing around project facilities.



Photo 5. View of sediment deposition on well pad and facilities from unstabilized cut-slope on northern edge of the well pad.





Photo 6. View of erosional channels on the cut-slope on the northern edge of the project area.



Photo 7. View of sediment deposition on the well pad downstream of the cut-slope on the northern edge of the well pad.





Photo 8. View of water ponding on the driving surface of the well pad.