

Site Photos (05-073-06567) 10/2/2014

Site location



Large weeds (Russian thistle) growing on top of soil stockpiles



Site Photos (05-073-06567) 10/2/2014

Side of access road bare of vegetation



Access road to John Craig 10-10 location



Site Photos (05-073-06567) 10/2/2014

Erosion riling along access road



Erosion from access road transporting sediment into adjacent pasture



Site Photos (05-073-06567) 10/2/2014

Culvert full of sediment



Culvert full of sediment

