

Inspector Name: Welsh, Brian

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE ET OE ES

Inspection Date:

10/20/2014

Document Number:

668500394

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	205770	321011	Welsh, Brian	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10383Name of Operator: SOVEREIGN OPERATING COMPANY LLCAddress: 475 17TH STREET #1200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Crane, Rocky	719-529-0682	rockycrane@yahoo.com	Pumper (BACA)
,	303-297-0347	sovereignenergy@aol.com	

Compliance Summary:QtrQtr: NESW Sec: 11 Twp: 31S Range: 44W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/18/2011	200308674	PR	PR	SATISFACTORY			No
05/05/2010	200248512	PR	PR	ACTION REQUIRED			Yes
04/22/2009	200209181	PR	PR	ACTION REQUIRED			Yes
01/02/2008	200124183	PR	PR	ACTION REQUIRED			Yes
12/13/2000	200012593	PR	PR	SATISFACTORY	I	Pass	No
03/03/1999	500135836	PR	PR			Pass	No
02/04/1998	500135835	PR	PR			Pass	No
12/26/1996	500135831	PR	PR				Yes
03/09/1995	500135834	PR	PR			Pass	Yes

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
114666	PIT		09/23/1999		-	PORTER 1-11	<input type="checkbox"/>
205770	WELL	PR	12/29/1977	GW	009-06184	PORTER 1-11	PR <input checked="" type="checkbox"/>

Equipment:Location Inventory

Inspector Name: Welsh, Brian

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	TWO TRACK ALONG FARM GROUND AND THROUGH CRP		

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	ACTION REQUIRED	WATER TANK NEEDS LABELING	Install sign to comply with rule 210.	11/20/2014
WELLHEAD	ACTION REQUIRED	LEASE SIGN ON METER RUN DOOR LAYING ON THE GROUND	Install sign to comply with rule 210.	11/20/2014

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
PUMP JACK	SATISFACTORY	HOG PANELS AROUND UNIT, WELLHEAD ANDELEC PANELS		

Equipment:					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Pump Jack	1	SATISFACTORY	CHURCHILL 40 ON 12" PLANKS		
Ancillary equipment	1	SATISFACTORY	ELECTRIC PANELS		
Gas Meter Run	1	SATISFACTORY	WEST OF UNIT		
Prime Mover	1	SATISFACTORY	ELECTRIC MOTOR		

Facilities: <input type="checkbox"/> New Tank Tank ID: _____					
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST	37.357610,-102.354820	

Inspector Name: Welsh, Brian

S/A/V:	SATISFACTORY	Comment:				
Corrective Action:					Corrective Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Corrective Action					Corrective Date	
Comment	BERMS WILL NEED MAINTENANCE					

<u>Venting:</u>			
Yes/No	Comment		

<u>Flaring:</u>					
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date	

Predrill

Location ID: 205770

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 205770 Type: WELL API Number: 009-06184 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING. CASING PRODUCTION

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Inspector Name: Welsh, Brian

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____
CA _____ CA Date _____
Waste Material Onsite? Pass CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Pass CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? _____ P _____

Inspector Name: Welsh, Brian

Comment: **UNUSED AREAS OF LOCATION ARE CRP**

Overall Interim Reclamation **Pass**

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Other	Pass			

S/A/V: SATISFACTOR _____ Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

ACTION REQUIRED

ANY ACTION REQUIRED items listed on this report indicate that the oil and gas facility or the oil and gas operations listed on the report may be in violation of the rules and regulations of the Colorado Oil and Conservation Commission (“COGCC”) and corrective action is required.

There is reasonable cause to believe that a violation of the Oil and Gas Conservation Act, or of any rule, regulation, or order of the Commission, or of any permit issued by the Commission, has occurred. The Operator’s compliance with this Inspection Report is required to resolve these alleged violations. This document requires the Operator to timely respond to the COGCC and to comply with directives as listed by the **Corrective Action Deadline Date**. Failure to do so will result in the issuance of a Notice of Alleged Violation and initiation of enforcement proceedings in which COGCC will seek monetary penalties for the alleged violations pursuant to § 34-60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1. (Please note that the COGCC's penalty authority was recently increased to a maximum of \$15,000 per day and penalties are no longer capped at a maximum of \$10,000 per violation.)