


**Site Photos (05-099-06285) 10/16/2014**

Looking South towards the location from the access road



Pipeline risers on North side of location





Site Photos (05-099-06285) 10/16/2014

Berm where tank battery was placed



Trash/wood debris and pile of gravel remain





**Site Photos (05-099-06285) 10/16/2014**

Center of location; well head remains



Center of location looking South; wood structure remains and plastic pipe





**Site Photos (05-099-06285) 10/16/2014**

Center of location looking East towards tank battery berm



At East side of location; stock tank is present





**Site Photos (05-099-06285) 10/16/2014**

Oil stained soil at center of location 37.92373/-102.69295



Looking West from center of location. Location bare of vegetation





**Site Photos (05-099-06285) 10/16/2014**

West side of location has a cut where dirt was removed



East side of location; erosion is developing transporting sediment into drainage channel

