



Photo 1. View of revegetation along the southern portion of the project area.



Photo 2. View of revegetation along the northern portion of the project area.



Photo 3. View of rill erosion and minimal revegetation on slopes above stream on western portion of project area.