



Photo 1. View of revegetation within the western portion of the project area.



Photo 2. View of revegetation within the northern portion of the project area and erosional channel within northwestern corner of project area.



Photo 3. View of kochia and Canada thistle in northeastern portion of project area.



Photo 4. View of musk thistle rosettes (in foreground) and mature thistles (in midground) within project area.