

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
10/28/2014Document Number:
666800221Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 210912 | 334992 | Murray, Richard | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|------------------------------|---------|
| Kellerby, Shaun | | shaun.kellerby@state.us.co | |
| Contact, General | | cogcc.inspections@encana.com | |

Compliance Summary:QtrQtr: NESW Sec: 2 Twp: 7S Range: 94W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 04/30/2013 | 663800932 | PR | PR | SATISFACTORY | | | No |
| 04/22/2011 | 200308977 | PR | PR | SATISFACTORY | | | No |
| 04/18/2011 | 200308908 | PR | PR | SATISFACTORY | | | No |
| 04/17/2000 | 200006987 | PR | PR | SATISFACTORY | | Pass | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|-------------------------------------|
| 111819 | PIT | | 09/23/1999 | | - | FEDERAL K-2-7-94-S | | <input type="checkbox"/> |
| 210912 | WELL | PR | 01/01/2005 | GW | 045-06670 | FEDERAL K-2-7-94-S | PR | <input checked="" type="checkbox"/> |
| 272757 | WELL | AL | 11/12/2013 | LO | 045-10148 | SAVAGE FED 2-314D | AL | <input checked="" type="checkbox"/> |
| 272758 | WELL | AL | 11/12/2013 | LO | 045-10147 | SAVAGE FED 2-324D | AL | <input checked="" type="checkbox"/> |

Equipment:**Location Inventory**

Inspector Name: Murray, Richard

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Equipment:

| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|-----------------------------|---|------------------------------|---------|-------------------|---------|
| Horizontal Heated Separator | 1 | SATISFACTORY | | | |
| Plunger Lift | 1 | SATISFACTORY | | | |

Venting:

| Yes/No | Comment |
|--------|---------|
| | |

Flaring:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
| | | | | |

Predrill

Location ID: 210912

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 210912 Type: WELL API Number: 045-06670 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 272757 Type: WELL API Number: 045-10148 Status: AL Insp. Status: AL

Facility ID: 272758 Type: WELL API Number: 045-10147 Status: AL Insp. Status: AL

Environmental**Spills/Releases:**

Inspector Name: Murray, Richard

| | | |
|-----------------------------------|--------------------|-------------------------------|
| Type of Spill: _____ | Description: _____ | Estimated Spill Volume: _____ |
| Comment: _____ | | |
| Corrective Action: _____ | | Date: _____ |
| Reportable: _____ | GPS: Lat _____ | Long _____ |
| Proximity to Surface Water: _____ | | Depth to Ground Water: _____ |

| | | | |
|------------------------|-------------------|-------------|------------|
| Water Well: | | Lat _____ | Long _____ |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ | _____ |

Field Parameters: _____

Sample Location: _____

| |
|---|
| Emission Control Burner (ECB): N _____ |
| Comment: _____ |
| Pilot: _____ Wildlife Protection Devices (fired vessels): YES _____ |

Reclamation - Storm Water - Pit

| | |
|--|--|
| Interim Reclamation: | |
| Date Interim Reclamation Started: _____ | Date Interim Reclamation Completed: _____ |
| Land Use: _____ | |
| Comment: _____ | |
| 1003a. Debris removed? _____ CM _____ | |
| CA _____ | CA Date _____ |
| Waste Material Onsite? _____ CM _____ | |
| CA _____ | CA Date _____ |
| Unused or unneeded equipment onsite? _____ CM _____ | |
| CA _____ | CA Date _____ |
| Pit, cellars, rat holes and other bores closed? _____ CM _____ | |
| CA _____ | CA Date _____ |
| Guy line anchors removed? _____ CM _____ | |
| CA _____ | CA Date _____ |
| Guy line anchors marked? _____ CM _____ | |
| CA _____ | CA Date _____ |
| 1003b. Area no longer in use? _____ | Production areas stabilized ? _____ |
| 1003c. Compacted areas have been cross ripped? _____ | |
| 1003d. Drilling pit closed? _____ | Subsidence over on drill pit? _____ |
| Cuttings management: _____ | |
| 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____ | |
| Production areas have been stabilized? _____ | Segregated soils have been replaced? _____ |
| RESTORATION AND REVEGETATION | |
| <u>Cropland</u> | |

Inspector Name: Murray, Richard

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT