

Site Photos (05-073-06113) 10/28/2014

Looking North from center of location



Looking West from center of location



Site Photos (05-073-06113) 10/28/2014

Looking South from center of location



Looking East from center of location



Site Photos (05-073-06113) 10/28/2014

Cattle guard still remains along access road to the location



Access road to the location still remains



Site Photos (05-073-06113) 10/28/2014

Weed growth (Russian thistle) along access road



Access road is mostly bare of vegetation and has compacted soils

