

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:
10/27/2014Document Number:
673707422Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 258004 | 317341 | Sherman, Susan | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 24500Name of Operator: PADCO LLCAddress: P O BOX 5275City: BEVERLY HILLS State: CA Zip: 90209-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|----------------|----------------------|--------------------------|
| Richmond, Dan | (918) 630-9912 | dan_dsrinc@cox.net | Field Operations Manager |
| Crumley, Tim | (970) 768-5658 | tcrumley@comcast.net | |

Compliance Summary:QtrQtr: SENW Sec: 28 Twp: 1S Range: 55W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 08/26/2014 | 673705796 | PR | SI | ACTION REQUIRED | I | | No |
| 01/21/2014 | 673700892 | PR | PR | ACTION REQUIRED | P | | No |
| 10/01/2012 | 663300630 | PR | PR | SATISFACTORY | P | | No |
| 09/28/2007 | 200119962 | PR | PR | SATISFACTORY | | | No |
| 02/27/2003 | 200035539 | PR | PR | SATISFACTORY | | Pass | No |
| 03/07/2001 | 200014789 | CO | PR | SATISFACTORY | I | Fail | Yes |
| 11/16/2000 | 200012207 | CO | PR | SATISFACTORY | I | Pass | Yes |
| 09/19/2000 | 200009801 | PR | WO | SATISFACTORY | | Fail | No |
| 09/12/2000 | 200010031 | DG | DG | SATISFACTORY | F | Pass | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 258004 | WELL | PR | 10/24/2000 | OW | 121-10629 | BACON 2-B | PA | <input checked="" type="checkbox"/> |

Equipment:**Location Inventory**

Inspector Name: Sherman, Susan

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Venting:

| | |
|--------|---------|
| Yes/No | Comment |
|--------|---------|

Flaring:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
|------|------------------------------|---------|-------------------|---------|

Predrill

Location ID: 258004

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 258004 Type: WELL API Number: 121-10629 Status: PR Insp. Status: PA

Cement**Cement Contractor**

Contractor Name: Yetter

Contractor Phone: 970-520-2885

Surface Casing

Cement Volume (sx):

Circulate to Surface:

Cement Fall Back:

Top Job, 1" Volume:

Intermediate Casing

Cement Volume (sxs):

Good Return During Job:

Production Casing

Cement Volume (sx):

Good Return During Job:

Plugging Operations

Depth Plugs(feet range): 4820'

Cement Volume (sx): 2

Good Return During Job: YES

Cement Type:

Comment: JW Wireline set CIBP at 4820' on 10/27/2014 and shot off casing at 2089.5' on 10/28/2014.
 10/29/2014
 Pumped 40 sxs, 14.5#, displaced with 11.5 BBL gel.
 Pumped 50 sxs, 15#, half in/half out, tagged at 66'.
 Pumped 15 sxs, 14.5#, displaced with 3 BBL, 1% CaCl to surface.
 10/30/2014
 One inch of fallback.

Environmental**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment: crop

1003a. Debris removed? Pass CM

CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass
 Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATIONCropland

Top soil replaced Pass Recontoured Pass Perennial forage re-established Pass

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: crop

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded In Contoured In Culverts removed In

Gravel removed In

Location and associated production facilities reclaimed In Locations, facilities, roads, recontoured In

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage In

Weeds present In Process Subsidence In

Comment: Tank battery in process of reclamation

Corrective Action: _____

Inspector Name: Sherman, Susan

| | | | | | | | |
|--|-----------------|-------------------------|-----------------------|--|--------------------------|--|--|
| | | | | | Date _____ | | |
| Overall Final Reclamation | | In Process | | Well Release on Active Location <input type="checkbox"/> | | Multi-Well Location <input type="checkbox"/> | |
| Storm Water: | | | | | | | |
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment | |
| | | | | | | | |
| S/A/V: _____ Corrective Date: _____ | | | | | | | |
| Comment: _____ | | | | | | | |
| CA: _____ | | | | | | | |
| Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT | | | | | | | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------------|---|
| 673707447 | PADCO Bacon 2B lease sign | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3473994 |
| 673707550 | PADCO Bacon 2B well sign | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3473995 |
| 673707551 | PADCO Bacon 2B Yetter rig | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3473996 |
| 673707680 | PADCO Bacon 2B PA | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3473997 |
| 673707681 | PADCO Bacon 2B PA | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3473998 |