

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:
11/03/2014Document Number:
674001711Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	292060	336346	Carlile, Craig	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Avant, Paul	(720) 929-6457	Paul.Avant@Anadarko.com	All Inspections
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Compliance Summary:QtrQtr: NENE Sec: 26 Twp: 3N Range: 68W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/20/2014	674001644	PR	PR	SATISFACTORY			No
04/05/2011	200308015	SR	PR	SATISFACTORY	I		No
03/25/2008	200129290	PR	PR	SATISFACTORY			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
278878	WELL	PR	02/11/2009	OW	123-23108	DOUTHIT 1-26	PR	<input checked="" type="checkbox"/>
292059	WELL	PR	12/07/2010	OW	123-26224	DOUTHIT 2-26	PR	<input checked="" type="checkbox"/>
292060	WELL	PR	12/07/2010	OW	123-26223	DOUTHIT 17-26	PR	<input checked="" type="checkbox"/>
292061	WELL	PR	06/09/2011	GW	123-26222	DOUTHIT 8-26	PR	<input checked="" type="checkbox"/>
292062	WELL	PR	12/27/2010	OW	123-26221	DOUTHIT 26-26	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Inspector Name: Carlile, Craig

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	Chainlink, Barb Top		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Plunger Lift	5	SATISFACTORY			

Facilities:

☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
			CENTRALIZED BATTERY	,

S/A/V: _____ Comment: Shared with API 05-123-26261

Corrective Action: _____ Corrective Date: _____

Paint

Condition	
-----------	--

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action: _____ Corrective Date: _____

Comment: _____

Inspector Name: Carlile, Craig

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 292060

Site Preparation:

Lease Road Adeq.: Pads: Soil Stockpile:

S/A/V:

Corrective Action: Date: CDP Num.:

Form 2A COAs:

S/A/V: **Comment:**

CA: **Date:**

Wildlife BMPs:

S/A/V: **Comment:**

CA: **Date:**

Stormwater:

Comment:

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: Address:

Phone Number: Cell Phone:

Operator Rep. Contact Information:

Landman Name: Phone Number:

Date Onsite Request Received: Date of Rule 306 Consultation:

Request LGD Attendance:

LGD Contact Information:

Name: Phone Number: Agreed to Attend:

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 278878 Type: WELL API Number: 123-23108 Status: PR Insp. Status: PR

Inspector Name: Carlile, Craig

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/A/V: SATISFACTORY CA Date: _____

CA: _____

Comment: Temporarily abandoned, due to nearby horizontal activity.

BradenHead

Comment: _____

CA: Plumbed to surface.

CA Date: _____

Facility ID: 292059 Type: WELL API Number: 123-26224 Status: PR Insp. Status: PR

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/A/V: SATISFACTORY CA Date: _____

CA: _____

Comment: Temporarily abandoned, due to nearby horizontal activity.

BradenHead

Comment: Plumbed to surface.

CA: _____

CA Date: _____

Facility ID: 292060 Type: WELL API Number: 123-26223 Status: PR Insp. Status: PR

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/A/V: SATISFACTORY CA Date: _____

CA: _____

Comment: Temporarily abandoned, due to nearby horizontal activity.

BradenHead

Comment: Plumbed to surface.

CA: _____

CA Date: _____

Facility ID: 292061 Type: WELL API Number: 123-26222 Status: PR Insp. Status: PR

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/A/V: SATISFACTORY CA Date: _____

CA: _____

Comment: Temporarily abandoned, due to nearby horizontal activity.

BradenHead

Comment: Plumbed to surface.

CA: _____

CA Date: _____

Facility ID: 292062 Type: WELL API Number: 123-26221 Status: PR Insp. Status: PR

Idle WellPurpose: ☒ Shut In☐ Temporarily Abandoned

Reminder: _____

S/A/V: _____

CA Date: _____

CA: _____

Comment: **Temporarily abandoned, due to nearby horizontal activity.****BradenHead**Comment: **Plumbed to surface.**

CA: _____

CA Date: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Inspector Name: Carlile, Craig

Guy line anchors marked? CM
CA CA Date

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped?

1003d. Drilling pit closed? Subsidence over on drill pit?

Cuttings management:

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?

Production areas have been stabilized? Segregated soils have been replaced?

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Recontoured Perennial forage re-established

Non-Cropland

Top soil replaced Recontoured 80% Revegetation

1003 f. Weeds Noxious weeds?

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Well plugged Pit mouse/rat holes, cellars backfilled

Debris removed No disturbance /Location never built

Access Roads Regraded Contoured Culverts removed

Gravel removed

Location and associated production facilities reclaimed Locations, facilities, roads, recontoured

Compaction alleviation Dust and erosion control

Non cropland: Revegetated 80% Cropland: perennial forage

Weeds present Subsidence

Comment:

Corrective Action: Date

Overall Final Reclamation Well Release on Active Location ☐ Multi-Well Location ☒

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

S/A/V: SATISFACTOR Corrective Date:

Y

Comment:

CA:

Inspector Name: Carlile, Craig

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Reinspection due to erroneous entry in corrective action field. Wells shut in due to horizontal activity.	carlilec	11/03/2014