



PHOTO: VIEW OF REFERENCE AREA

CAMERA ANGLE: NORTHERLY



PHOTO: VIEW OF REFERENCE AREA

CAMERA ANGLE: EASTERLY

EXTRACTION OIL & GAS

**BURROUGHS SOUTH #13, #12, #11, #10, #9 & #8
SECTION 14, T7N, R65W, 6th P.M.
SE 1/4 NE 1/4**



UELS, LLC
Corporate Office * 85 South 200 East
Vernal, UT 84078 * (435) 789-1017

DRAWN BY: T.W.	DATE DRAWN: 06-26-14
TAKEN BY: D.N.	REVISED: 00-00-00
REFERENCE AREA PHOTOS	REF 1



PHOTO: VIEW OF REFERENCE AREA

CAMERA ANGLE: SOUTHERLY



PHOTO: VIEW OF REFERENCE AREA

CAMERA ANGLE: WESTERLY

EXTRACTION OIL & GAS

**BURROUGHS SOUTH #13, #12, #11, #10, #9 & #8
SECTION 14, T7N, R65W, 6th P.M.
SE 1/4 NE 1/4**



UELS, LLC
Corporate Office * 85 South 200 East
Vernal, UT 84078 * (435) 789-1017

DRAWN BY: T.W.	DATE DRAWN: 06-26-14
TAKEN BY: D.N.	REVISED: 00-00-00
REFERENCE AREA PHOTOS	REF 2