



Photo 1. View of Canada thistle (*Cirsium arvense*) plants growing within the project area.





Photo 2. View of Scotch thistle (*Onopordum acanthium*) plants growing within the project area.





Photo 3. View of large Russian thistle (*Salsola tragus*) plants at the entrance to the project area that are drying and will soon break off and become debris.





Photo 4. View of sediment discharge from the western portion of the project area.





Photo 5. View of stormwater diversion channel in southwestern portion of project area that needs BMPs to de-energize and filter stormwater flows.