

Site Photos (05-073-06504) 10/28/2014

Raptor #3 location



Southeast corner of the pit



Site Photos (05-073-06504) 10/28/2014

Northeast corner of location



Surface roughening around the location



Site Photos (05-073-06504) 10/28/2014

Southwest corner of location



East side of location. Location was properly fenced



Site Photos (05-073-06504) 10/28/2014

Dust from access road

