

Site Photos (05-071-09373) (05-071-09374)

11/7/2014

Access road to the location

photo #1



Access road is not recontoured and has sparse vegetation

photo #2



Site Photos (05-071-09373) (05-071-09374)

11/7/2014

Erosion rills running down the access road

photo #3



Access road is not recontoured and has sparse vegetation

photo #4



Site Photos (05-071-09373) (05-071-09374)

11/7/2014

Access road at the Southeast corner of the location

photo #5



Southeast corner of location facing Northwest

photo #6



Site Photos (05-071-09373) (05-071-09374)

11/7/2014

Looking West at the South side of the location

photo #7



Looking off the edge of the pad on the South side of the location

photo #8



Site Photos (05-071-09373) (05-071-09374)

11/7/2014

Center of location facing North

photo #9



Center of location facing West

photo #10



Site Photos (05-071-09373) (05-071-09374)

11/7/2014

Center of location facing South

photo #11



Center of location facing East

photo #12



Site Photos (05-071-09373) (05-071-09374)

11/7/2014

Open pits on the North side of the location

photo #13



Open pits on the North side of the location

photo #14



Site Photos (05-071-09373) (05-071-09374)

11/7/2014

Northwest corner of the location

photo #15



Northeast corner of the location facing West

photo #16



Site Photos (05-071-09373) (05-071-09374)

11/7/2014

Northeast corner of the location

photo #17



East side of the location facing Northwest

photo #18



Site Photos (05-071-09373) (05-071-09374)

11/7/2014

Bottom, Southeast base of the pad

photo #19



Soil stockpile adjacent to the access road

photo #20

