

API 045-06290 Rifle Walton 25-2 Inspection Photos 11/7/2014



Wellhead sign on tank access stairs



Rifle Walton 25-2 wellhead



Bradenhead vent pipe and regulator system. Insulation on location at time of inspection is a little bit of straw and a piece of plywood. The $\frac{1}{4}$ " pipe is plumbed from the casing at 2200psi.





Regulators at time of inspection. 2200 psi on production casing.
Two regulators are attached to surface casing. The one to the right read 50 psi.



Produced water tank at time of inspection. Required labeling and placard not provided.