

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:
11/17/2014Document Number:
674700599Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335965	335965	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10516Name of Operator: LINN OPERATING INCAddress: 1999 BROADWAY SUITE 3700City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Johnson, Derek	970-285-2200	dsjohnson@linnenergy.com	
White, Brent		bwhite@linnenergy.com	Production Foreman
Bang, Heidi	303-999-4262	HBang@linnenergy.com	
Burns, Bryan		bburns@linnenergy.com	

Compliance Summary:QtrQtr: NENW Sec: 29 Twp: 5S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/02/2014	663903275			SATISFACTORY			No
09/18/2013	663902210			SATISFACTORY	F		No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
287089	WELL	XX	05/23/2013	LO	045-12878	CHEVRON 29-13D	ND	<input checked="" type="checkbox"/>
287090	WELL	XX	05/23/2013	LO	045-12877	CHEVRON 29-14D	ND	<input checked="" type="checkbox"/>
287091	WELL	PR	01/11/2010	GW	045-12876	CHEVRON 29-15D	PR	<input checked="" type="checkbox"/>
287092	WELL	XX	05/23/2013	LO	045-12875	CHEVRON 29-16D	ND	<input checked="" type="checkbox"/>
287093	WELL	XX	05/23/2013	LO	045-12874	CHEVRON 29-7D	ND	<input checked="" type="checkbox"/>
287094	WELL	XX	05/23/2013	LO	045-12873	CHEVRON 29-8D	ND	<input checked="" type="checkbox"/>
287095	WELL	PR	01/11/2010	GW	045-12872	CHEVRON 29-12D	PR	<input checked="" type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

287096	WELL	PR	02/13/2012	GW	045-12871	CHEVRON 29-11D	PR	<input checked="" type="checkbox"/>
298426	WELL	PR	02/13/2012	GW	045-17201	CHEVRON 29-3D	PR	<input checked="" type="checkbox"/>
298427	WELL	XX	05/23/2013	LO	045-17202	CHEVRON 29-5D	ND	<input checked="" type="checkbox"/>
298428	WELL	XX	05/23/2013	LO	045-17203	CHEVRON 29-6D	ND	<input checked="" type="checkbox"/>
420685	PIT		09/03/2009		-	CHEVRON CD-29		<input type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>11</u>	Production Pits: <u>1</u>
Condensate Tanks: <u>3</u>	Water Tanks: <u>2</u>	Separators: <u>2</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: <u>1</u>
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
CONTAINERS	SATISFACTORY			
BATTERY	SATISFACTORY			
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
LOCATION	SATISFACTORY	Around seeded reclamation		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Horizontal Heated Separator	4	SATISFACTORY			
Ancillary equipment	1	SATISFACTORY			
Plunger Lift	4	SATISFACTORY			

Inspector Name: LONGWORTH, MIKE

Bird Protectors	8	SATISFACTORY			
-----------------	---	--------------	--	--	--

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
----------	---	----------	------	--------

CONDENSATE	1	200 BBLS	PBV STEEL	,
------------	---	----------	-----------	---

S/A/V:		Comment:	
--------	--	----------	--

Corrective Action:		Corrective Date:	
--------------------	--	------------------	--

Paint

Condition	
-----------	--

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
----------	---	----------	------	--------

CONDENSATE	4	300 BBLS	HEATED STEEL AST	,
------------	---	----------	------------------	---

S/A/V: SATISFACTORY	Comment:	
---------------------	----------	--

Corrective Action:		Corrective Date:	
--------------------	--	------------------	--

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 335965

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
OGLA	kubeczko	<p>GENERAL ROAN RIM COAs:</p> <p>Notify the COGCC Oil and Gas Location Assessment (OGLA) Specialist for Western Colorado (Dave Kubeczko; email dave.kubeczko@state.co.us) and the COGCC Field Inspection Supervisor for Northwest Colorado (Shaun Kellerby; email shaun.kellerby@state.co.us) 48 hours prior to start of construction.</p> <p>Reserve pit, or any other pit used to contain/hold fluids, if constructed, must be lined or a closed loop system (as indicated on the Form 2A Permit application by operator in Section 6. Construction) must be implemented during drilling.</p> <p>The nearby hillside must be monitored for any day-lighting of drilling fluids throughout the drilling of the surface casing interval.</p> <p>Operator must ensure 110 percent secondary containment for any volume of fluids contained at well site during drilling and completion operations; including, but not limited to, construction of a berm or diversion dike, diversion/collection trenches within and/or outside of berms/dikes, site grading, or other comparable measures (i.e., best management practices (BMPs) associated with stormwater management) sufficiently protective of nearby surface water. Any berm constructed at the well pad location will be stabilized, inspected at regular intervals (at least every 14 days), and maintained in good condition.</p> <p>The moisture content of any drill cuttings in a cuttings pit, trench, or pile shall be as low as practicable to prevent accumulation of liquids greater than de minimis amounts. At the time of closure, the drill cuttings must also meet the applicable standards of table 910-1.</p> <p>No portion of any pit that will be used to hold liquids shall be constructed on fill material, unless the pit and fill slope are designed and certified by a professional engineer, subject to review and approval by the director prior to construction of the pit. The construction and lining of the pit shall be supervised by a professional engineer or their agent. The entire base of the pit must be in cut.</p> <p>Flowback and stimulation fluids must be sent to tanks to allow the sand to settle out before the fluids can be placed into any pipeline or pit located on the well pad. The flowback and stimulation fluid tanks must be placed on the well pad in an area with additional downgradient perimeter berming. The area where flowback fluids will be stored/reused must be constructed to be sufficiently impervious to contain any spilled or released material (per Rule 604.a.(4)). In addition, operator must implement odor controls during fracing operations.</p> <p>Notify the COGCC Oil and Gas Location Assessment (OGLA) Specialist for Western Colorado (Dave Kubeczko; email dave.kubeczko@state.co.us) and the COGCC Field Inspection Supervisor for Northwest Colorado (Shaun Kellerby; email shaun.kellerby@state.co.us) 48 hours prior to start of fracing operations.</p> <p>Berms or other containment devices shall be constructed in compliance with Rule 604.a.(4) around crude oil, condensate, and produced water storage tanks.</p>	02/07/2011

OGLA	kubeczkod	SENSITIVE AREA (CLOSE PROXIMITY TO SURFACE WATER) COAs: Location is in a sensitive area because of close proximity to surface water, therefore, operator must ensure 110 percent secondary containment for any volume of fluids contained at well site during drilling and completion operations. Operator must implement best management practices to contain any unintentional release of fluids, including any fluids conveyed via temporary surface pipelines.	02/07/2011
OGLA	kubeczkod	NOTICE TO OPERATORS (NTO) DRILLING WELLS ON THE ROAN PLATEAU IN GARFIELD COUNTY: Comply with all provisions of the June 12, 2008 Notice to Operators (NTO) Drilling Wells Within ¼ Mile of the Rim of the Roan Plateau in Garfield County – Pit Design, Construction, and Monitoring Requirements. At a minimum, the following condition of approval (COA) will apply: All pits (if constructed) must be lined.	02/07/2011

S/A/V: SATISFACTORY**Comment:**

Production tanks and chemical containers inside of berm and secondary containment

CA:**Date:****Wildlife BMPs:**

BMP Type	Comment
Drilling/Completion Operations	<p>The following list of Best Management Practices (BMP's) that will be implemented by Berry Petroleum Company during the pad construction, well drilling, well completion, natural gas production and reclamation phases of activity on the Chevron CD-29 596 well Pad. A total of 11 wells have and/or will be directionally drilled from the CD-29 well pad. Directional drilling has enabled Berry Petroleum Company to reduce the number of well pads required for gas recovery and will minimize surface damage.</p> <p>The CD-29 well pad will be constructed adjacent to an existing road. This eliminates the need to construct an additional road for access and avoids additional surface disturbance.</p> <p>In general, Berry Petroleum Company will comply with all applicable federal, state and local statutes, rules, regulations and ordinances, including those of OSHA, the COGCC and the CDPHE. Relating to safety and the environment.</p> <p>During construction of the well pad, topsoil will be isolated from other soils and placed and stacked per COGCC requirements. All cuts, fill slopes, pits and topsoil piles will be stabilized and revegetated immediately following construction.</p> <p>The pad will be constructed in compliance with CDPHE Stormwater Discharge regulations. The reserve/completion pit will be fenced/flagged and/or netted to prevent entry of wildlife (including birds) and livestock.</p> <p>Bear proof dumpsters/trash cans will be used on the location for solid/food waste disposal. Noxious weeds will be controlled.</p> <p>Temporary housing for the drill rig crews will meet all Garfield County regulations. The housing quarters will receive 24/7 supervision by Berry Petroleum Company.</p> <p>Production tanks shall be placed on a non-permeable liner and surrounded by a metal containment wall at least 3 feet in height.</p>

S/A/V: SATISFACTORY**Comment:**

7 open conductors

CA:**Date:****Stormwater:****Comment:****Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Inspector Name: LONGWORTH, MIKE

Landman Name: _____	Phone Number: _____
Date Onsite Request Received: _____	Date of Rule 306 Consultation: _____
Request LGD Attendance: _____	
<u>LGD Contact Information:</u>	
Name: _____	Phone Number: _____ Agreed to Attend: _____
<u>Summary of Landowner Issues:</u>	
<u>Summary of Operator Response to Landowner Issues:</u>	
<u>Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:</u>	

Facility

Facility ID: 287089	Type: WELL	API Number: 045-12878	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Facility ID: 287090	Type: WELL	API Number: 045-12877	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Facility ID: 287091	Type: WELL	API Number: 045-12876	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Facility ID: 287092	Type: WELL	API Number: 045-12875	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Facility ID: 287093	Type: WELL	API Number: 045-12874	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Facility ID: 287094	Type: WELL	API Number: 045-12873	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Facility ID: 287095	Type: WELL	API Number: 045-12872	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Facility ID: 287096	Type: WELL	API Number: 045-12871	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Facility ID: 298426	Type: WELL	API Number: 045-17201	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Facility ID: 298427	Type: WELL	API Number: 045-17202	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Facility ID: 298428	Type: WELL	API Number: 045-17203	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Environmental

Spills/Releases:

Inspector Name: LONGWORTH, MIKE

Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: _____		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____		Depth to Ground Water: _____

Water Well:		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	_____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:	
Date Interim Reclamation Started: _____	Date Interim Reclamation Completed: _____
Land Use: RANGELAND	
Comment: _____	
1003a. Debris removed? _____ CM _____	
CA _____	CA Date _____
Waste Material Onsite? _____ CM _____	
CA _____	CA Date _____
Unused or unneeded equipment onsite? _____ CM _____	
CA _____	CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____	
CA _____	CA Date _____
Guy line anchors removed? _____ CM _____	
CA _____	CA Date _____
Guy line anchors marked? _____ CM _____	
CA _____	CA Date _____
1003b. Area no longer in use? _____	Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	Subsidence over on drill pit? _____
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____	
Production areas have been stabilized? _____	Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION	
<u>Cropland</u>	

Inspector Name: LONGWORTH, MIKE

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Seeding	Pass					
		Check Dams	Pass	MHSP	Pass	
		Compaction				
		Ditches				
Berms	Pass					
Gravel	Pass					
Ditches	Pass					
Compaction	Pass					
		Gravel				

S/A/V: SATISFACTOR _____

Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Inspector Name: LONGWORTH, MIKE

Permit:	Facility ID	Permit Num	Expiration Date
	420685	1171084	
	420685	1171084	