

Site Photos: API# 05-071-08144

Date: November 7, 2014




photo 1: Montoya 41-1V



photo 2: Looking East at location. Unused pipe left on location.

Site Photos: API# 05-071-08144

Date: November 7, 2014



photo 3: Shed panel has fallen over.



photo 4: Sediment trap at the Southeast corner of location is filled with sediment.

Site Photos: API# 05-071-08144

Date: November 7, 2014



photo 5: Chain used to measure freeboard is installed in pit.



photo 6: Southeast corner of location looking west at location.

Site Photos: API# 05-071-08144

Date: November 7, 2014



photo 7: Erosion rill developing off the South side of location.



photo 8: Vegetation on the West side of location facing to the North.