

Reference Area Photographs

Inspection Conducted on November 21, 2014

**Maralex
Rifle Boulton 1
Location ID #322369
API 045 06127**

Maralex Rifle Boulton I



Identification by the produced water tank



Proper signs on location. Some weeds within the bermed area (Secondary containment

Rifle Boulton I



Well has no protection, no sign. API number not displayed on site.
MIT conducted recently.



Temporary separator is been removed. Original separator has been repaired, pressure tested and will be re-installed.

Rifle Boulton I



Remote control flowmeter has been upgraded.



Large area not in use, toward the end of the pad (Noreast), should eventually be reclaimed. Some weed in the pad and around equipment.