



Photo 1. View of revegetation along southeastern portion of project area. Vegetation here is comprised of species such as intermediate wheatgrass (*Elymus hispidus*), cheatgrass (*Bromus tectorum*), Russian thistle (*Salsola tragus*), and Indian ricegrass (*Achnatherum hymenoides*).





Photo 2. View of woody debris stockpiled along southeastern edge of project area.





Photo 3. View of revegetation work along southeastern edge of working area from eastern corner of project area facing westward.





Photo 4. View of reclaimed area from northern edge of the project area facing center.